

---

---

# *Assignment Questions*

---

---

**Information:** The text pages that you are to study are provided at the beginning of the assignment questions.



COMMANDING OFFICER  
NETPMSA  
6490 SAUFLEY FIELD RD  
PENSACOLA FL 32509-5237

Errata No. 2

3 February 1993

Specific Instructions and Errata for  
Nonresident Training Course

Aviation Structural Mechanic E 2

1. TO OBTAIN CREDIT FOR DELETED QUESTIONS, SHOW THIS ERRATA TO YOUR LOCAL COURSE ADMINISTRATOR (ESO/SCORER). THE LOCAL COURSE ADMINISTRATOR (ESO/SCORER) IS DIRECTED TO CORRECT THE ANSWER KEY FOR THIS COURSE BY INDICATING THE QUESTIONS DELETED.
2. This errata supersedes all previous errata. No attempt has been made to issue corrections for errors in typing, punctuation, and so forth, which do not affect your ability to answer the questions.
3. Assignment Booklet

Delete the following questions and leave the corresponding spaces blank on the answer sheets.

Questions

4-61  
5-41  
7-50  
7-51

Make the following changes:

Question

Change

1-25

In the question, line 3, change the word "compressurization" to "overpressurization."

1-51

In choice 4, change "chamber A" to "chamber C."

1-65

In choices 2 and 4, change "psi" to "psia."

Question

Change

2-50	In column A, under "Functions" change to read "Operates on nitrogen pressure received from the canopy pneumatic control module and canopy pneumatic timer."
3-6	In choice 4, change "The vent bleeder valve" to read "The vent bleeder check valve."
3-10	In choice 4, add "above pressure regulator" after "psi."
4-34 to 4-38, Instructions for	For questions 4-34 through 4-38, refer to "FIGURE 3-2" instead of "FIGURE 4-2."
5-48	In choice 2, "change the word "slack" to read "black."
7-7	In choice 4, change the word "ON" to read "Test mask."
8-31	In choice 3, change "115/120" to "115/200."